

ENVIRONMENTAL PROTECTION AGENCY

STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

US EPA RECORDS CENTER REGION 5



498848

INSPECTION REPORT - SITE INVENTORY NO. 14380801

(11) (18)

Peoria Co. - L.P.C.

Region # C
(19)Date 091479
(20) (25)Peoria / Janson
(Location) (Responsible Party)Letter Sent (Yes or No) N
(26)Samples Taken: Yes (X) No () Time: From 01:55 PM
Ground Water() Surface() Other() To 02:50 PM
Photos Taken: Yes (X) No () Interviewed C.M. Janson

Weather clear 70s°

Inspector J P T
MMN (27) (29)

Previous Inspection 8-17-79 Previous Correspondence 3-20-78 Site Open: Yes() No(X)

OPERATIONAL STATUS:	TYPE OF OPERATION:	AUTHORIZATION:
Operating ()	Sanitary Landfill (X)	E.P.A. Permit (X) DE
Temporarily Closed (X)	Random Dump ()	Variance ()
Closed Not Covered ()	Other ()	21(e) ()
Closed and Covered ()	Quantity Received Daily(1-6) 1	Board Order ()
	(30)	Illegal (5) (X) 5
		(31)

SITE EVALUATION

Leachate: Pounded on site (X)	32
Flowing on site (X)	33
Seeping (X)	34
Evidence of past flows (X)	35
Observed garbage() refuse() in standing water (X)	36
Flow entering surface water (5)	37
Flow leaving site (1-3)	38
Open Burning: Observed (5)	39
Underground fire (5)	40
Evidence of recent open burning (5)	41
Insufficient fire protection equipment provided (2)	42
Daily Cover: Not provided on previously deposited refuse (5)	43
Not provided on previous operating day (4)	44
Inadequate depth over entire area (3)	45
Inadequate depth over only a portion of area (1-2)	46
Intermediate Cover: Inadequate depth in portion(s) (X) or entire() required areas (1-3)	47
Final Cover: Inadequate depth in some areas (1-3)	48
Inadequate depth over entire area 60 days after area closure (4)	49
None 60 days after area closure (5)	50
Unloading not supervised (3)	51
Refuse not deposited at toe of slope ()	
Inadequate spreading and compacting ()	
Insufficient operable equipment on site as required (X) (2 ea. 2-8)	52
Operational roads unsatisfactory ()	
Blowing litter(), dust nuisance observed(), Odor detected (X) (1 ea. 1-3)	53
Permit() Board Order(X) Violation noted (2 ea. 2-4)	54
Liquids() Solids(X) not permitted (5)	55
Inadequate site restriction(X) Site concealment() (2 ea. 2-4)	56
Inadequate: Shelter() Sanitary Facilities() Emergency Communications() (1 ea. 1-3)	57
Scavenging by: Operator() Others() observed (1-3)	58
Salvaging Observed(): Improperly conducted in: Location() Operation() Storage() (1-3)	59
Evidence of vectors observed () (1-3)	60
Animal feeding observed () (1-3)	61

General Compliance () Improvement Needed (X) Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

DATE: September 14, 1979

TO: Division File

FROM: Monte Nienkerk

SUBJECT: Peoria County - LPC#14380801 - Peoria/Janson

The Janson landfill located just southwest of Peoria on Kickapoo Creek was visited on September 14, 1979. We arrived at the site at 2:00p.m. The following people were in attendance:

Arthur Daniels - John Sexton Contractors
Ann Carr - AG's Office
Howard Martin - AG's Office
Steve Woods - AG's Office
Bill Child - IEPA
Monte Nienkerk - IEPA
John Taylor - IEPA

Nobody representing the land fill was present. It was apparent that work had been done at adding cover material to the west central area of the site. Cracks were observed in this cover material, at the top of the fill. These cracks are about four feet in from the break of the slope. A blue-white vapor was emanating from these cracks. This vapor had the smell of burnt refuse. The ground surface temperature was taken directly over one of these cracks. This temperature was 130°F. The thermometer was lowered into a crack. At a depth of 8 inches, the temperature was 190°F. At a depth of 18 inches, below ground surface, the temperature was measured to be 195°F. It should be noted that during normal decomposition at a landfill, temperatures do not rise above 160°F.

Use of detector tubes to determine if carbon monoxide (CO) is being produced was not possible because of the high temperatures. The results of the CO detector tubes on the August 17, 1979, visit to the site are most likely invalid because of the high temperatures.

Three air samples were collected from below surface by inserting tubing into a crack and attaching evacuated glass containers to the tubing. These samples were delivered to the Springfield IEAP laboratory for analysis for the presence of methane, carbon monoxide, and carbon dioxide.

CC: ✓ Central Region
Enforcement Programs
LandFOS Manager
Ann Carr, AG's Office

mmr/cg

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

0-2
8/17/79

INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)

Peoria

Co. - L.P.C.

Region # C
(19)

Date 081779
(20) (25)

Peoria / Janson

(Location) (Responsible Party)

Letter Sent (Yes or No) 1
(26)

Samples Taken: Yes (X) No () Time: From 11:55 AM
Ground Water () Surface () Other () To 02:30 PM
Photos Taken: Yes (X) No () Interviewed CM Janson

Weather clear 80°

Inspector J P T
MMN (27) (29)

Previous Inspection 8-9-79 Previous Correspondence 3-20-78 Site Open: Yes () No (X)

OPERATIONAL STATUS: TYPE OF OPERATION: AUTHORIZATION:
Operating () Sanitary Landfill (X) Storage () E.P.A. Permit (X) DE
Temporarily Closed (X) Random Dump () Salvage () Variance ()
Closed Not Covered () Other () A.C.D. () 21(e) ()
Closed and Covered () Quantity Received Daily (1-6) 1 Board Order ()
(30) Illegal (5) (X) 5
(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32
Flowing on site (X) 33
Seeping (X) 34
Evidence of past flows (X) 35
Observed garbage () refuse () in standing water (X) 36
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4)* 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s) (X) or entire () required areas (1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope ()
Inadequate spreading and compacting ()
Insufficient operable equipment on site as required (X) (2 ea. 2-8) 52 2
Operational roads unsatisfactory ()
Blowing litter (), dust nuisance observed (), Odor detected (X) (1 ea. 1-3) 53 1
Permit () Board Order (X) Violation noted (2 ea. 2-4) 54 2
Liquids () Solids (X) not permitted (5) 55 5
Inadequate site restriction (X) Site concealment () (2 ea. 2-4) 56 2
Inadequate: Shelter () Sanitary Facilities () Emergency Communications () (1 ea. 1-3) 57
Scavenging by: Operator () Others () observed (1-3) 58
Salvaging Observed (): Improperly conducted in: Location () Operation () Storage () (1-3) 59
Evidence of vectors observed () (1-3) 60
Animal feeding observed () (1-3) 61

General Compliance () Improvement Needed (X) Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

DATE: August 17, 1979
TO: Division File
FROM: Monte M. Nienkerk
SUBJECT: Peoria County- LPC 14380801 - Peoria/Janson

On August 17, 1979, an on site meeting was held to discuss possible solutions to the problems occurring at the Janson landfill near Peoria. The following people were in attendance:

- Charles Janson, site operator
- Ed Wright, Limestone Township Fire Chief
(did not arrive until 2:00p.m.)
- From the Attorney General's Office
- Ann Carr
- From IEPA
- Monte Nienkerk
- John Taylor
- Ken Mensing
- from John Sexton Contractors
- Arthur Daniels, Executive Vice President
- Alfred Gallo, General Counsel
- William Jackson, Regional Superintendent

The people from Sexton were at the site to assess the problem and give recommendations on correcting the situation.

We arrived at the site at approximately 1:00p.m. Mr. Janson plus three of his sons were already on the site. The entire site was surveyed and in the opinion of the people from Sexton there was an underground fire occurring. Mr. Janson disagreed with this and refused to listen to any suggestions on correcting the problem.

All except for Mr. Janson and his sons left the site at approximately 2:00p.m.

I returned to the site at approximately 2:40p.m. to collect air samples. Mr. Janson and his sons were still present at the site and he observed my actions. The point selected to collect the sample was from a crack in the cover material at the south end of the site.

Using a three foot steel probe, I inserted it into the crack approximate two feet. The purpose of this was to make a passage hole so that tubing used to collect the air sample could be inserted into the cover material.

Page 2

Before collecting the air sample, I used a Kitagawa #106 carbon monoxide (CO), color intensity, detector tube to determine if any CO was being produced by the site. I inserted the tube into the hole made by the steel probe and drew the samples into the detector tube. Using temperature and sample time corrections, the color intensity indicated that there was CO being produced at the site.

At 2:50p.m. I inserted tubing into the hole approximately two feet, and using glass cylinders which had been evacuated, I collected two samples. These samples were delivered to the Springfield IEPA laboratory at 6:20p.m.

MMN/cg

cc: Central Region ✓
Enforcement Services
A. Carr, AG's Office

L P C F C O 5 5 C
(1) (8) (9)INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)Peoria

CO. - L.P.C.

Region # CDate 07/24/79
(20) (25)Peoria1Janson

(Location)

(Responsible Party)

Letter Sent (Yes or No) N
(26)Samples Taken: Yes () No (☒) Time: From 11:08 AMWeather partly cloudy 80°Ground Water() Surface() Other() To 11:57 AMPhotos Taken: Yes (☒) No () Interviewed Charles JansonInspector J P T
(27) (29)Previous Inspection 4-20-79 Previous Correspondence 3-20-78 Site Open: Yes(☒) No()

OPERATIONAL STATUS: TYPE OF OPERATION:

AUTHORIZATION:

Operating (☒) Landfill (☒) Storage () E.P.A. Permit (☒) DE

Temporarily Closed () Random Dump () Salvage () Variance ()

Closed Not Covered () Other () A.C.D. () 21(e) ()

Closed and Covered () Quantity Received Daily(1-6) 1 Board Order ()(30) Illegal (5) (☒) 5
(31)

IMPROVED

SAME


DETERIORATED

I S or D S
(62)

GENERAL REMARKS: Operating general refuse site with only a DE Permit. Site is still accepting general refuse at odd hours and is now accepting shredder waste from the A. Miller Co. Janson thinks it's dirt! (or so he claims) The underground fire continues to burn. Janson thinks it is "steam". He plans to do nothing about it. For further details see the July 24, 1979 memo concerning this site.

INTERVIEW:

DIAGRAM:



Peoria County


LPC 14380801

DATE: July 24, 197

Peoria

Janson

TIME: 11:08-11:57





ENVIRONMENTAL PROTECTION AGENCY • STATE OF ILLINOIS

INSPECTION REPORT - SITE INVENTORY NO. 14380801PCORIA

CO. - L.P.C.

Region # 3Inspector TOBERMAN(Location) PCORIA / 1 (Responsible Party) JANSONSamples Taken: Yes () No (☒)Photographs Taken: Yes (☒) No ()Date 5-14-74 Time 2:15 Weather CLDY-60° Interviewed MR. JANSON, NOT AVAILABLE
Previous Inspection 4-2-74 Previous Correspondence 3-15-74 Site Open: Yes () No (☒)

AUTHORIZATION:

E.P.A. Permit ()
Variance ()
None (☒)

TYPE OF OPERATION:

Sanitary Landfill (☒) Storage ()
Random Dump () Salvage ()
Other OPEN DUMP A.C.D. ()

OPERATIONAL STATUS:

Operating (☒)
Temporarily Closed ()
Permanently Closed ()
Closed and Covered ()

SITE EVALUATION

Open Dumping of Garbage () Refuse () Observed
Openly Dumped Garbage (☒) Refuse (☒) Observed
Open Burning () Evidence of Recent Open Burning () Observed
Observed Dumping of Garbage () Refuse () into Standing Water
Observed Garbage () Refuse () in Standing Water
Evidence of a Water Pollution Hazard Observed ()
Hazardous () Liquid () Waste Accepted at Site
Leachate Pond or Stream Observed () Leachate Leaving Site ()
Blowing Litter Observed ()
Observed Evidence of Vectors (☒) FLIES & RATS Dust Nuisance ()
Scavenging Observed () By Operator () By Others ()
Salvage Area () Operations () Storage () Unsatisfactory
Odor Present (☒) GARBAGE
Permit () Board Order () Violation NotedTHREE RATS WERE
ENCOUNTERED DURING
THE INSPECTION.Cover Applied to Refuse Daily Yes () No (☒)
Daily Cover of Adequate Depth Yes () No (☒)
Cover Material of Adequate Quality Yes () No (☒) ACTUALLY THERE DOESN'T APPEAR TO BE SUFFICIENT COVER ON SITE.
Final Cover Applied in Required Areas Yes () No (☒)
Final Cover of Adequate Depth Yes () No (☒)
Intermediate Cover Applied in Required Areas Yes () No (☒)
Intermediate Cover of Adequate Depth Yes () No (☒)
Site Access Restricted Yes (☒) No ()
Spreading and Compacting Adequate Yes () No (☒)
Site Fencing Adequate Yes (☒) No ()
Site Posted Yes (☒) No ()
Operational (☒) Access (☒) Road(s) Satisfactory Yes (☒) No ()
Adequate Shelter (☒) Sanitary Facilities (☒) Provided Yes (☒) No () @ ST CLAIR HOUSE
Site Policing () Portable Fencing () Provided Yes () No (☒)
Unloading Supervised Yes (☒) No ()
Operable Equipment Present on Site Yes () No () EQUIP. ON SITE - NOT SURE IF IT IS OPERABLE
Fire Protection Equipment Provided ? - THE LOCAL FIRE DEPT. HAS STATED THAT THEY WILL NOT ANSWER CALLS @ SITE Yes () No ()
General Compliance () MUCH, MUCH, Improvement Needed NO Improvement Observed

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)Peoria

Co. - L.P.C.

Region # C
(19)Date 062278
(20) (25)Peoria/ Janson

(Location)

(Responsible Party)

Letter Sent (Yes or No) N
(26)Samples Taken: Yes () No (☒) Time: From 02:30 P MWeather clear 80s°Ground Water () Surface () Other () To 02:55 P MPhotos Taken: Yes (☒) No () Interviewed operatorsInspector J P T
(27) (29)Previous Inspection 6-21-78 Previous Correspondence 3-20-78 Site Open: Yes (☒) No ()

OPERATIONAL STATUS: TYPE OF OPERATION:

AUTHORIZATION:

Operating (☒) Sanitary Landfill (☒) Storage ()

E.P.A. Permit ()

Temporarily Closed () Random Dump () Salvage ()

Variance ()

Closed Not Covered () Other () A.C.D. ()

21(e) ()

Closed and Covered () Quantity Received Daily(1-6) 1

Board Order ()

(30)

Illegal (5) (☒) 5
(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32 X
Flowing on site (X) 33
Seeping (X) 34 X
Evidence of past flows (X) 35 X
Observed garbage(☒) refuse(☒) in standing water (X) 36 X
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4) 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s) (☒) or entire () required areas (1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope (☒)
Inadequate spreading and compacting (☒)
Insufficient operable equipment on site as required () (2 ea. 2-8) 52 4
Operational roads unsatisfactory ()
Blowing litter (), dust nuisance observed (), Odor detected () (1 ea. 1-3) 53
Permit () Board Order (☒) Violation noted (2 ea. 2-4) 54 2
Liquids () Solids (☒) not permitted (5) 55 5
Inadequate site restriction () Site concealment (☒) (2 ea. 2-4) 56 2
Inadequate: Shelter () Sanitary Facilities () Emergency Communications () (1 ea. 1-3) 57
Scavenging by: Operator () Others () observed (1-3) 58
Salvaging Observed (): Improperly conducted in: Location () Operation () Storage () (1-3) 59
Evidence of vectors observed (☒) (1-3) RATS 60 1
Animal feeding observed () (1-3) 61

General Compliance ()

Improvement Needed (☒)

Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. 14-360661
(11) (18)

Co. - L.P.C.

Region # C
(19)

Date 02-22-78
(20) (25)

Letter Sent (Yes or No) N
(26)

(Location) (Responsible Party)

Samples Taken: Yes () No (X) Time: From 02:30 P M

Weather cloudy 80°

Ground Water () Surface () Other () To 02:55 P M

Photos Taken: Yes (X) No () Interviewed

Inspector J P T
(27) (29)

Previous Inspection 6-21-78 Previous Correspondence 3-20-78 Site Open: Yes (X) No ()

OPERATIONAL STATUS:	TYPE OF OPERATION:	AUTHORIZATION:
Operating (X)	Sanitary Landfill (X) Storage ()	E.P.A. Permit ()
Temporarily Closed ()	Random Dump () Salvage ()	Variance ()
Closed Not Covered ()	Other () A.C.D. ()	21(e) ()
Closed and Covered ()	Quantity Received Daily (1-6) 1	Board Order ()
	(30)	Illegal (5) (X) 5

SITE EVALUATION

<u>Leachate:</u>	Ponded on site (X)	32	X
	Flowing on site (X)	33	
	Seeping (X)	34	X
	Evidence of past flows (X)	35	X
	Observed garbage(X) refuse(X) in standing water (X)	36	X
	Flow entering surface water (5)	37	
	Flow leaving site (1-3)	38	
<u>Open Burning:</u>	Observed (5)	39	
	Underground fire (5)	40	5
	Evidence of recent open burning (5)	41	
	Insufficient fire protection equipment provided (2)	42	
<u>Daily Cover:</u>	Not provided on previously deposited refuse (5)	43	5
	Not provided on previous operating day (4)	44	4
	Inadequate depth over entire area (3)	45	3
	Inadequate depth over only a portion of area (1-2)	46	
<u>Intermediate Cover:</u>	Inadequate depth in portion(s)(X) or entire() required areas(1-3)	47	3
<u>Final Cover:</u>	Inadequate depth in some areas (1-3)	48	4
	Inadequate depth over entire area 60 days after area closure (4)	49	
	None 60 days after area closure (5)	50	
	Unloading not supervised (3)	51	
	Refuse not deposited at toe of slope (X)		
	Inadequate spreading and compacting (X)		
	Insufficient operable equipment on site as required () (2 ea. 2-8)	52	4
	Operational roads unsatisfactory ()		
	Blowing litter(), dust nuisance observed(), Odor detected() (1 ea. 1-3)	53	
	Permit() Board Order(X) Violation noted (2 ea. 2-4)	54	2
	Liquids() Solids(X) not permitted (5)	55	5
	Inadequate site restriction() Site concealment(X) (2 ea. 2-4)	56	2
	Inadequate: Shelter() Sanitary Facilities() Emergency Communications() (1 ea.1-3)	57	
	Scavenging by: Operator() Others() observed (1-3)	58	
	Salvaging Observed():Improperly conducted in:Location()Operation()Storage() (1-3)	59	
	Evidence of vectors observed (X) (1-3) RATS	60	1
	Animal feeding observed () (1-3)	61	

General Compliance () Improvement Needed (X) Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

PEORIA CO.

LPC


14380801

DATE: June 22, 19

PEORIA

JANSON

TIME: 2:30-2:55



MEMORANDUM

DATE: June 22, 1978
TO: Division File
FROM: John Taylor
SUBJECT: Peoria County - LPC 14380801 - Peoria/Janson

The Janson Landfill site was inspected on June 21 and June 22, 1978 by John Taylor. The site was again observed to be in violation of the Act, the Rules, Board Order No. PCB 76-292, and Permit No. 1975-41-DE in numerous ways.

The site has large areas of exposed refuse that have not been covered all around the site. The surface area of the exposed refuse appears to be approximately 4,900 square yards or slightly over one acre. Some old uncovered areas from several years ago would increase this figure somewhat but those areas are overgrown with weeds, making observation difficult. No attempt at covering was detected on either day of the inspection. The site appears to be deficient in available cover material and the situation is worsening as they are hauling material off of the site for use elsewhere. Walter Deemie's trucks hauling demolition waste onto the site are being loaded with earth before they leave. Apparently this soil is being used to backfill foundations of demolished structures.

Old filled areas still are in need of intermediate and final cover. Some of the recently filled areas have probably lain exposed for over 60 days and are in violation of Rules 305(b) and 305(c) also.

A lot of the open dumped refuse at the site was neither deposited at the toe of the slope nor was it adequately spread and compacted in violation of Rules 303(a) and 303(b).

As was previously mentioned, the site appears to be operating in violation of Pollution Control Board Order No. PCB 76-292. The respondent, Charles Janson, has not paid the \$6,000.00 penalty. The other directive, Part 2 of the Order, orders Janson to cease and desist further violations of the Act and the Rules. This may no longer apply as Janson has not been seen on the site and it is rumored that he may not own the property that is being filled. If he has personally relinquished ownership of the property and does not legally control dumping activities there, it may be necessary to prepare yet another action before the Board against whoever does.

Substantial amounts of waste from an auto shredder were observed open dumped at the site. This material apparently comes from I. Bork and Sons auto shredder in Peoria.

The site is a true eyesore as open dumped refuse can be easily seen from nearby Creek Road and also from Lincoln Avenue north of the site. Also, rats were observed at the site on June 22, 1978 by John Taylor, in violation of Rule 314(f).

The site is in as bad a condition as it ever has been and no improvement can be expected. The only positive aspect is that the underground fire in the northeast corner of the site appears to be shrinking in size. Everything else appears to be worse.

JT:kb/4127A,3-4

cc: Land FOS Manager ✓
Central Region
Enforcement Programs
Environmental Control Division

Date: June 22, 1978

Time: 2:30 - 2:55 P.M.

Photograph By:

John Taylor

Location: LPC- 14380801

Peoria

Co.

Peoria

/ Janson

Comments: Photograph taken

toward the southwest from
the southeast area of
the site.



Date: June 22, 1978

Time: 2:30 - 2:55 P.M.

Photograph By:

John Taylor

Location: LPC- 14380801

Peoria

Co.

Peoria

/ Janson

Comments: Photograph taken

oward the southwest from
the southeast area of
the site.



Date: June 22, 1978

Time: 2:30 - 2:55 P.M.

Photograph By:

John Taylor

Location: LPC- 14380801

Peoria Co.

Peoria / Janson

Comments: Photograph taken

toward the northwest from
the southeast area of
the site.



Date: June 22, 1978

Time: 2:30 - 2:55 P.M.

Photograph By:

John Taylor

Location: LPC- 14380801

Peoria Co.

Peoria / Janson

Comments: Photograph taken

toward the southeast in the
north area of the site.



Date: June 22, 1978

Time: 2:30 - 2:55 P.M.

Photograph By:

John Taylor

Location: LPC- 14380801

Peoria Co.

Peoria / Janson


Comments: Photograph taken

toward the north in the

north area of the site

Rat at left center.

Backwards



Site: _____

Name: _____

Photograph By:

Location: LPC-

Co.

Comments: Photograph taken

toward the

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. 14380801

Peoria

CO. - L.P.C.

Region # 3

Date 01/12/77

Peoria

1 Jenson
(Location) (Responsible Party)

Letter Sent (Yes or No) N
(26)

Samples Taken: Yes (X) No () NA Time: From 11:00 am

Weather 0° windy - snow

Ground Water () Surface () Other () To 12:00 pm

Photos Taken: Yes () No (X) Interviewed Charles Jenson

Inspector G E S
(27) (28) (29)

Previous Inspection 12-10-76 Previous Correspondence 12-29-76 Site Open: Yes (X) No ()

OPERATIONAL STATUS: TYPE OF OPERATION:

Operating (X)	Landfill (X)	Storage ()
Temporarily Closed ()	Random Dump ()	Salvage ()
Closed Not Covered ()	Other ()	A.C.D. ()
Closed and Covered ()	Quantity Received Daily (1-6) <u>2</u>	
	(30)	

AUTHORIZATION:

E.P.A. Permit (X) DE
Variance ()
21(e) ()
Board Order ()
Illegal (5) (X) 5
(31)

IMPROVED

SAME

DETERIORATED underground fire - daily & found cover


I S or D D
(62)

GENERAL REMARKS: underground fire in berm adjacent to
Kickapoo Creek. Operating area area fill on
N.E. corner. Exposed refuse in central & on S.W.
side of site with snow cover.

Took Dräger readings on smoke - CO. 500ppm 70
1500ppm. NH₃ 5ppm. H₂S - no reading at 5ft.

INTERVIEW: Discussed fire, digging it out with Jenson.
Discussed permit & daily operations.

DIAGRAM:



Date: January 12, 1977

Time: 11:15 am.

Photograph By:

M. S. Stauffer

Location: 14380801
Peoria County
Peoria/Janson

Comments:

*Taken towards
the Northeast.*



Date: January 12, 1977

Time: 11:25 am.

Photograph By:

M. S. Stauffer

Location: 14380801
Peoria County
Peoria/Janson

Comments:

*Taken towards
the Northeast.*



ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

US EPA RECORDS CENTER REGION 5



498848

INSPECTION REPORT - SITE INVENTORY NO. 14380801

(11)

(18)

Peoria

Co. - L.P.C.

Region #

(19)

Date 091479

(20)

(25)

Peoria

/ Janson

Letter Sent (Yes or No)

(26)

(Location)

(Responsible Party)

Samples Taken: Yes (X) No ()

Time: From 01:55 PM

Weather clear 70s°

Ground Water () Surface () Other ()

To 02:50 PM

Photos Taken: Yes (X) No ()

Interviewed C.M. Janson

Inspector J P T

MMN

(27)

(29)

Previous Inspection 8-17-79

Previous Correspondence 3-20-78

Site Open: Yes () No (X)

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating ()

Sanitary Landfill (X)

Storage ()

E.P.A. Permit (X) DE

Temporarily Closed (X)

Random Dump ()

Salvage ()

Variance ()

Closed Not Covered ()

Other ()

A.C.D. ()

21(e) ()

Closed and Covered ()

Quantity Received Daily(1-6)

(30)

Board Order ()

Illegal (5)

(X) 5

(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32
Flowing on site (X) 33
Seeping (X) 34
Evidence of past flows (X) 35
Observed garbage () refuse () in standing water (X) 36
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4) 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s) (X) or entire () required areas (1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope ()
Inadequate spreading and compacting ()
Insufficient operable equipment on site as required (X) (2 ea. 2-8) 52 2
Operational roads unsatisfactory ()
Blowing litter (), dust nuisance observed (), Odor detected (X) (1 ea. 1-3) 53 1
Permit () Board Order (X) Violation noted (2 ea. 2-4) 54 2
Liquids () Solids (X) not permitted (5) 55 5
Inadequate site restriction (X) Site concealment () (2 ea. 2-4) 56 2
Inadequate: Shelter () Sanitary Facilities () Emergency Communications () (1 ea. 1-3) 57
Scavenging by: Operator () Others () observed (1-3) 58
Salvaging Observed (): Improperly conducted in: Location () Operation () Storage () (1-3) 59
Evidence of vectors observed () (1-3) 60
Animal feeding observed () (1-3) 61

General Compliance ()

Improvement Needed (X)

Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

DATE: September 14, 1979

TO: Division File

FROM: Monte Nienkerk

SUBJECT: Peoria County - LPC#14380801 - Peoria/Janson

The Janson landfill located just southwest of Peoria on Kickapoo Creek was visited on September 14, 1979. We arrived at the site at 2:00p.m. The following people were in attendance:

Arthur Daniels - John Sexton Contractors
Ann Carr - AG's Office
Howard Martin - AG's Office
Steve Woods - AG's Office
Bill Child - IEPA
Monte Nienkerk - IEPA
John Taylor - IEPA

Nobody representing the land fill was present. It was apparent that work had been done at adding cover material to the west central area of the site. Cracks were observed in this cover material, at the top of the fill. These cracks are about four feet in from the break of the slope. A blue-white vapor was emanating from these cracks. This vapor had the smell of burnt refuse. The ground surface temperature was taken directly over one of these cracks. This temperature was 130°F. The thermometer was lowered into a crack. At a depth of 8 inches, the temperature was 190°F. At a depth of 18 inches, below ground surface, the temperature was measured to be 195°F. It should be noted that during normal decomposition at a landfill, temperatures do not rise above 160°F.

Use of detector tubes to determine if carbon monoxide (CO) is being produced was not possible because of the high temperatures. The results of the CO detector tubes on the August 17, 1979, visit to the site are most likely invalid because of the high temperatures.

Three air samples were collected from below surface by inserting tubing into a crack and attaching evacuated glass containers to the tubing. These samples were delivered to the Springfield IEAP laboratory for analysis for the presence of methane, carbon monoxide, and carbon dioxide.

CC: ~~Central~~ Central Region
Enforcement Programs
LandFOS Manager
Ann Carr, AG's Office

mna/cg

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

8/17/79

INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)

Peoria

Co. - L.P.C.

Region # C
(19)

Date 081779
(20) (25)

Peoria

/ Janson

Letter Sent (Yes or No) V
(26)

(Location) (Responsible Party)

Samples Taken: Yes (X) No () Time: From 11:55 AM
Ground Water() Surface() Other() To 02:30 PM
Photos Taken: Yes (X) No () Interviewed CM Janson

Weather clear 80°

Inspector J P T
MMN (27) (29)

Previous Inspection 8-9-79 Previous Correspondence 3-20-78 Site Open: Yes() No(X)

OPERATIONAL STATUS: TYPE OF OPERATION:
Operating () Sanitary Landfill (X) Storage ()
Temporarily Closed (X) Random Dump () Salvage ()
Closed Not Covered () Other () A.C.D. ()
Closed and Covered () Quantity Received Daily(1-6) 1
(30)

AUTHORIZATION:
E.P.A. Permit (X) DE
Variance ()
21(e) ()
Board Order ()
Illegal (5) (X) 5
(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32
Flowing on site (X) 33
Seeping (X) 34
Evidence of past flows (X) 35
Observed garbage() refuse() in standing water (X) 36
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4)* 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s)(X) or entire() required areas(1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope ()
Inadequate spreading and compacting ()
Insufficient operable equipment on site as required (X) (2 ea. 2-8) 52 2
Operational roads unsatisfactory ()
Blowing litter(), dust nuisance observed(), Odor detected(X) (1 ea. 1-3) 53 1
Permit() Board Order(X) Violation noted (2 ea. 2-4) 54 2
Liquids() Solids(X) not permitted (5) 55 5
Inadequate site restriction(X) Site concealment() (2 ea. 2-4) 56 2
Inadequate: Shelter() Sanitary Facilities() Emergency Communications() (1 ea. 1-3) 57
Scavenging by: Operator() Others() observed (1-3) 58
Salvaging Observed(): Improperly conducted in: Location() Operation() Storage() (1-3) 59
Evidence of vectors observed () (1-3) 60
Animal feeding observed () (1-3) 61

General Compliance () Improvement Needed (X) Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature _____ Owner/Operator _____



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

DATE: August 17, 1979
TO: Division File
FROM: Monte M. Nienkerk
SUBJECT: Peoria County- LPC 14380801 - Peoria/Janson

On August 17, 1979, an on site meeting was held to discuss possible solutions to the problems occurring at the Janson landfill near Peoria. The following people were in attendance:

- Charles Janson, site operator
- Ed Wright, Limestone Township Fire Chief
(did not arrive until 2:00p.m.)
- From the Attorney General's Office
- Ann Carr
- From IEPA
- Monte Nienkerk
- John Taylor
- Ken Mensing
- from John Sexton Contractors
- Arthur Daniels, Executive Vice President
- Alfred Gallo, General Counsel
- William Jackson, Regional Superintendent

The people from Sexton were at the site to assess the problem and give recommendations on correcting the situation.

We arrived at the site at approximately 1:00p.m. Mr. Janson plus three of his sons were already on the site. The entire site was surveyed and in the opinion of the people from Sexton there was an underground fire occurring. Mr. Janson disagreed with this and refused to listen to any suggestions on correcting the problem.

All except for Mr. Janson and his sons left the site at approximately 2:00p.m.

I returned to the site at approximately 2:40p.m. to collect air samples. Mr. Janson and his sons were still present at the site and he observed my actions. The point selected to collect the sample was from a crack in the cover material at the south end of the site.

Using a three foot steel probe, I inserted it into the crack approximately two feet. The purpose of this was to make a passage hole so that tubing used to collect the air sample could be inserted into the cover material.

Page 2

Before collecting the air sample, I used a Kitagawa #106 carbon monoxide (CO), color intensity, detector tube to determine if any CO was being produced by the site. I inserted the tube into the hole made by the steel probe and drew the samples into the detector tube. Using temperature and sample time corrections, the color intensity indicated that there was CO being produced at the site.

At 2:50p.m. I inserted tubing into the hole approximately two feet, and using glass cylinders which had been evacuated, I collected two samples. These samples were delivered to the Springfield IEPA laboratory at 6:20p.m.

MMN/cg

cc: Central Region ✓
Enforcement Services
A. Carr, AG's Office

L P C F C O 5 5 C
(1) (8) (9)INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)Peoria

CO. - L.P.C.

Region # CDate 07/24/79
(20) (25)Peoria1Janson

(Location)

(Responsible Party)

Letter Sent (Yes or No) N
(26)Samples Taken: Yes () No (☒)Time: From 11:08 AMWeather partly cloudy 80°

Ground Water () Surface () Other ()

To 11:57 AMPhotos Taken: Yes (☒) No ()Interviewed Charles JansonInspector J P T
(27) (29)Previous Inspection 4-20-79Previous Correspondence 3-20-78Site Open: Yes (☒) No ()

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (☒)Landfill (☒)

Storage ()

E.P.A. Permit (☒) DE

Temporarily Closed ()

Random Dump ()

Salvage ()

Variance ()

Closed Not Covered ()

Other ()

A.C.D. ()

21(e) ()

Closed and Covered ()

Quantity Received Daily(1-6) 1

(30)

Board Order ()

Illegal (5) (☒) 5

(31)

IMPROVED

SAME


DETERIORATED

I S or D S
(62)

GENERAL REMARKS: Operating general refuse site with only a DE Permit. Site is still accepting general refuse at odd hours and is now accepting shredder waste from the A. Miller Co. Janson thinks it's dirt! (or so he claims) The underground fire continues to burn. Janson thinks it is "steam". He plans to do nothing about it. For further details see the July 24, 1979 memo concerning this site.

INTERVIEW:

DIAGRAM:



Peoria County


LPC 14380801

DATE: July 24, 197

Peoria

Janson

TIME: 11:08-11:57



C. & N.W. RR.

Low Area

Shredder Waste

Kickapoo Creek

Smoke vents
in these general
areas

Scale 1"=100'



ENVIRONMENTAL PROTECTION AGENCY • STATE OF ILLINOIS

INSPECTION REPORT - SITE INVENTORY NO. 14380801PCURIA

CO. - L.P.C.

Region # 3Inspector TOBERMANPCURIA

(Location)

1 JASON

(Responsible Party)

Samples Taken: Yes () No (X)

Photographs Taken: Yes (X) No ()

Date 5-14-74 Time 2:15 Weather CLDY-60° Interviewed MR JASON NOT AVAILABLEPrevious Inspection 4-2-74 Previous Correspondence 3-15-74 Site Open: Yes () No (X)

AUTHORIZATION:

E.P.A. Permit ()

Variance ()

None (X)

TYPE OF OPERATION:

Sanitary Landfill (X) Storage ()

Random Dump () Salvage ()

Other OPEN DUMP A.C.D. ()

OPERATIONAL STATUS:

Operating (X)

Temporarily Closed ()

Permanently Closed ()

Closed and Covered ()

SITE EVALUATION

Open Dumping of Garbage () Refuse () Observed
Openly Dumped Garbage (X) Refuse (X) Observed
Open Burning () Evidence of Recent Open Burning () Observed
Observed Dumping of Garbage () Refuse () into Standing Water
Observed Garbage () Refuse () in Standing Water
Evidence of a Water Pollution Hazard Observed ()
Hazardous () Liquid () Waste Accepted at Site
Leachate Pond or Stream Observed () Leachate Leaving Site ()
Blowing Litter Observed ()
Observed Evidence of Vectors (X) FLIES & RATS Dust Nuisance ()
Scavenging Observed () By Operator () By Others ()
Salvage Area () Operations () Storage () Unsatisfactory
Odor Present (X) GARBAGE
Permit () Board Order () Violation Noted

THREE RATS WERE
ENCOUNTERED DURING
THE INSPECTION.

Cover Applied to Refuse Daily Yes () No (X)
Daily Cover of Adequate Depth Yes () No (X)
Cover Material of Adequate Quality Yes () No (X) ACTUALLY, THERE DOESN'T APP-
Final Cover Applied in Required Areas Yes () No (X) EAR TO BE SUFFICIENT COV-
Final Cover of Adequate Depth Yes () No (X) ON SITE.
Intermediate Cover Applied in Required Areas Yes () No (X)
Intermediate Cover of Adequate Depth Yes () No (X)
Site Access Restricted Yes (X) No ()
Spreading and Compacting Adequate Yes () No (X)
Site Fencing Adequate Yes (X) No ()
Site Posted Yes (X) No ()
Operational (X) Access (X) Road(s) Satisfactory Yes (X) No ()
Adequate Shelter (X) Sanitary Facilities (X) Provided Yes (X) No () @ ST CLAIR HOUSE
Site Policing () Portable Fencing () Provided Yes () No (X)
Unloading Supervised Yes (X) No ()
Operable Equipment Present on Site Yes () No () EQUIP. ON SITE - NOT SURE
Fire Protection Equipment Provided ? - THE LOCAL FIRE DEPT. HAS STATED THAT THEY WILL NOT ANSWER CALLS @ SITE Yes () No () IF IT IS OPERABLE
General Compliance () MUCH, MUCH Improvement Needed NO Improvement Observed

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)Peoria

Co. - L.P.C.

Region # C
(19)Date 062278
(20) (25)Peoria/ JansonLetter Sent (Yes or No) N
(26)

(Location)

(Responsible Party)

Samples Taken: Yes () No (X) Time: From 02:30 P m
Ground Water() Surface() Other() To 02:55 P m
Photos Taken: Yes (X) No () Interviewed operatorsWeather clear 80s°Inspector J P T
(27) (29)Previous Inspection 6-21-78 Previous Correspondence 3-20-78 Site Open: Yes (X) No ()

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (X) Sanitary Landfill (X) Storage ()
Temporarily Closed () Random Dump () Salvage ()
Closed Not Covered () Other () A.C.D. ()
Closed and Covered () Quantity Received Daily(1-6) 1
(30)E.P.A. Permit ()
Variance ()
21(e) ()
Board Order ()
Illegal (5) (X) 5
(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32 X
Flowing on site (X) 33
Seeping (X) 34 X
Evidence of past flows (X) 35 X
Observed garbage(X) refuse(X) in standing water (X) 36 X
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4) 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s)(X) or entire() required areas(1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope (X)
Inadequate spreading and compacting (X)
Insufficient operable equipment on site as required () (2 ea. 2-8) 52 4
Operational roads unsatisfactory ()
Blowing litter(), dust nuisance observed(), Odor detected() (1 ea. 1-3) 53
Permit() Board Order(X) Violation noted (2 ea. 2-4) 54 2
Liquids() Solids(X) not permitted (5) 55 5
Inadequate site restriction() Site concealment(X) (2 ea. 2-4) 56 2
Inadequate: Shelter() Sanitary Facilities() Emergency Communications(-) (1 ea.1-3) 57
Scavenging by: Operator() Others() observed (1-3) 58
Salvaging Observed():Improperly conducted in:Location()Operation()Storage() (1-3) 59
Evidence of vectors observed (X) (1-3) RATS 60 1
Animal feeding observed () (1-3) 61

General Compliance ()

Improvement Needed (X)

Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. 14360661

(11) (18)

Co. - L.P.C.

Region #

Date 042278

(19)

(20)

(25)

Letter Sent (Yes or No) N

(26)

(Location)

(Responsible Party)

Samples Taken: Yes () No (X)

Time: From 02:30 P m

Weather clear 80°

Ground Water () Surface () Other ()

To 02:55 P m

Photos Taken: Yes (X) No ()

Interviewed

Inspector J P T

(27)

(29)

Previous Inspection 6-21-78

Previous Correspondence 3-20-78

Site Open: Yes (X) No ()

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (X)

Sanitary Landfill (X)

Storage ()

E.P.A. Permit ()

Temporarily Closed ()

Random Dump ()

Salvage ()

Variance ()

Closed Not Covered ()

Other ()

A.C.D. ()

21(e) ()

Closed and Covered ()

Quantity Received Daily (1-6) 1

Board Order ()

Illegal (5) (X) 5

(30)

SITE EVALUATION

(31)

Leachate: Ponded on site (X) 32 X

Flowing on site (X) 33

Seeping (X) 34 X

Evidence of past flows (X) 35 X

Observed garbage (X) refuse (X) in standing water (X) 36 X

Flow entering surface water (5) 37

Flow leaving site (1-3) 38

Open Burning: Observed (5) 39

Underground fire (5) 40 5

Evidence of recent open burning (5) 41

Insufficient fire protection equipment provided (2) 42

Daily Cover: Not provided on previously deposited refuse (5) 43 5

Not provided on previous operating day (4) 44 4

Inadequate depth over entire area (3) 45 3

Inadequate depth over only a portion of area (1-2) 46

Intermediate Cover: Inadequate depth in portion(s) (X) or entire () required areas (1-3) 47 3

Final Cover: Inadequate depth in some areas (1-3) 48 3

Inadequate depth over entire area 60 days after area closure (4) 49

None 60 days after area closure (5) 50

Unloading not supervised (3) 51

Refuse not deposited at toe of slope (X)

Inadequate spreading and compacting (X)

Insufficient operable equipment on site as required () (2 ea. 2-8) 52 4

Operational roads unsatisfactory ()

Blowing litter (), dust nuisance observed (), Odor detected () (1 ea. 1-3) 53

Permit () Board Order (X) Violation noted (2 ea. 2-4) 54 2

Liquids () Solids (X) not permitted (5) 55 5

Inadequate site restriction () Site concealment (X) (2 ea. 2-4) 56 2

Inadequate: Shelter () Sanitary Facilities () Emergency Communications () (1 ea. 1-3) 57

Scavenging by: Operator () Others () observed (1-3) 58

Salvaging Observed (): Improperly conducted in: Location () Operation () Storage () (1-3) 59

Evidence of vectors observed (X) (1-3) 60 1

Animal feeding observed () (1-3) 61

General Compliance ()

Improvement Needed (X)

Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature


Owner/Operator

PEORIA CO. - LPC 14380801

DATE: June 22, 19

PEORIA JANSON

TIME: 2:30 - 2:55 P.



MEMORANDUM

DATE: June 22, 1978
TO: Division File
FROM: John Taylor
SUBJECT: Peoria County - LPC 14380801 - Peoria/Janson

The Janson Landfill site was inspected on June 21 and June 22, 1978 by John Taylor. The site was again observed to be in violation of the Act, the Rules, Board Order No. PCB 76-292, and Permit No. 1975-41-DE in numerous ways.

The site has large areas of exposed refuse that have not been covered all around the site. The surface area of the exposed refuse appears to be approximately 4,900 square yards or slightly over one acre. Some old uncovered areas from several years ago would increase this figure somewhat but those areas are overgrown with weeds, making observation difficult. No attempt at covering was detected on either day of the inspection. The site appears to be deficient in available cover material and the situation is worsening as they are hauling material off of the site for use elsewhere. Walter Deemie's trucks hauling demolition waste onto the site are being loaded with earth before they leave. Apparently this soil is being used to backfill foundations of demolished structures.

Old filled areas still are in need of intermediate and final cover. Some of the recently filled areas have probably lain exposed for over 60 days and are in violation of Rules 305(b) and 305(c) also.

A lot of the open dumped refuse at the site was neither deposited at the toe of the slope nor was it adequately spread and compacted in violation of Rules 303(a) and 303(b).

As was previously mentioned, the site appears to be operating in violation of Pollution Control Board Order No. PCB 76-292. The respondent, Charles Janson, has not paid the \$6,000.00 penalty. The other directive, Part 2 of the Order, orders Janson to cease and desist further violations of the Act and the Rules. This may no longer apply as Janson has not been seen on the site and it is rumored that he may not own the property that is being filled. If he has personally relinquished ownership of the property and does not legally control dumping activities there, it may be necessary to prepare yet another action before the Board against whoever does.

Substantial amounts of waste from an auto shredder were observed open dumped at the site. This material apparently comes from I. Bork and Sons auto shredder in Peoria.

The site is a true eyesore as open dumped refuse can be easily seen from nearby Creek Road and also from Lincoln Avenue north of the site. Also, rats were observed at the site on June 22, 1978 by John Taylor, in violation of Rule 314(f).

The site is in as bad a condition as it ever has been and no improvement can be expected. The only positive aspect is that the underground fire in the northeast corner of the site appears to be shrinking in size. Everything else appears to be worse.

JT:kb/4127A,3-4

cc: Land FOS Manager ✓
Central Region
Enforcement Programs
Environmental Control Division



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

DATE: January 12, 1977
TO: File
FROM: Central Region - Gilbert E. Stauffer
SUBJECT: PEORIA COUNTY 14380801
Peoria / Janson

On this date, John Taylor and I met Charles Janson at his landfill on the west edge of Peoria.

The underground fire was pointed out to Mr. Janson on the northeast corner of the site. The fire was in the berm adjacent to Kickapoo Creek.

Mr. Janson stated that "someone" had told him the site was producing steam, not smoke. He stated only demo material was in the area that was smoking.

A Drager Multi-Gas Detector was used to analyze the smoke. A reading of 500ppm to 1500 ppm CO was obtained.

The area of the fire indicated some settling of the surface. A definite smoke odor was noted. The smoke did not dissipate quickly, but lingered in the area. The cracks observed in the surface were charred along the edges.

It was explained to Mr. Janson that an underground fire was in progress and should be dug out and extinguished.

The developmental permit and site operation were also discussed.

Mr. Janson stated he would try to work on the fire as soon as weather permitted.

GES:bac

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C
(1) (8) (9)INSPECTION REPORT - SITE INVENTORY NO. 14380801
(11) (18)Peoria

Co. - L.P.C.

Region # C
(19)Date 100479
(20) (25)Letter Sent (Yes or No) N
(26)

(Location)

(Responsible Party)

Samples Taken: Yes () No (☒) Time: From 11:10AMGround Water() Surface() Other() To 11:53AMPhotos Taken: Yes (☒) No () Interviewed Charles JansonWeather partly cloudy 40s°Inspector J P T
(27) (29)Previous Inspection 9-21-79 Previous Correspondence 3-20-78 Site Open: Yes() No(☒)

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating ()

Temporarily Closed (☒)

Closed Not Covered ()

Closed and Covered ()

~~Sanitary Landfill~~ (☒)

Random Dump ()

Other ()

Quantity Received Daily(1-6) 1

Storage ()

Salvage ()

A.C.D. ()

E.P.A. Permit (☒ DE)

Variance ()

21(e) ()

Board Order ()

Illegal (5) (☒ 5)
(31)

SITE EVALUATION

Leachate: Ponded on site (X) 32
Flowing on site (X) 33
Seeping (X) 34
Evidence of past flows (X) 35
Observed garbage() refuse() in standing water (X) 36
Flow entering surface water (5) 37
Flow leaving site (1-3) 38
Open Burning: Observed (5) 39
Underground fire (5) 40 5
Evidence of recent open burning (5) 41
Insufficient fire protection equipment provided (2) 42
Daily Cover: Not provided on previously deposited refuse (5) 43 5
Not provided on previous operating day (4) 44 4
Inadequate depth over entire area (3) 45 3
Inadequate depth over only a portion of area (1-2) 46
Intermediate Cover: Inadequate depth in portion(s)() or entire(☒) required areas(1-3) 47 3
Final Cover: Inadequate depth in some areas (1-3) 48 3
Inadequate depth over entire area 60 days after area closure (4) 49
None 60 days after area closure (5) 50
Unloading not supervised (3) 51
Refuse not deposited at toe of slope ()
Inadequate spreading and compacting ()
Insufficient operable equipment on site as required (☒) (2 ea. 2-8) 52 2
Operational roads unsatisfactory ()
Blowing litter(), dust nuisance observed(), Odor detected(☒) (1 ea. 1-3) 53 1
Permit() Board Order(☒) Violation noted (2 ea. 2-4) 54
Liquids() Solids(☒) not permitted (5) 55 5
Inadequate site restriction(☒) Site concealment() (2 ea. 2-4) 56 2
Inadequate: Shelter() Sanitary Facilities() Emergency Communications() (1 ea.1-3) 57
Scavenging by: Operator() Others() observed (1-3) 58
Salvaging Observed():Improperly conducted in:Location()Operation()Storage() (1-3) 59
Evidence of vectors observed () (1-3) 60
Animal feeding observed () (1-3) 61

General Compliance ()

Improvement Needed (☒)

Improvement Observed ()

Signature of operator does not necessarily imply agreement with the above noted observations.

Signature

Owner/Operator

Peoria County

LPC 14380801

DATE: October 4, 1979

Peoria

Janson

TIME: 11:10 - 11:53

C. & N.W. RR.

"Cut"
in berm

Smoke
venting
observed

Randomly
dumped
refuse?

Additional material
excavated from
bluff

Randomly dumped
refuse?

subsidence
area
(warm to the
touch)

Refuse excavated
from low
area? ± 5 yd²

Smoke
venting
observed

Smoke
Venting
Observed

Partially
burned
newspapers
July 12, 13
8 9th 1979
in this
area

Some
excavation
of refuse
(± 8 bucket loads)

Center Low Area

Smoke Venting
observed

Smoke venting observed

Kickapoo Creek

Scale 1" = 100'



DATE: October 4, 1979

TO: Division File

FROM: John Taylor

SUBJECT: PEORIA CO./LPC -- #14380801
PEORIA/JANSON

? The Janson dump was inspected on October 4, 1979, by John Taylor. The site was observed to be in essentially the same condition as previously observed over the last two (2) months.

The underground fire appears to be continuing in the previously noted areas and there is some evidence that it may be spreading in the northeast area of the site. New smoke vents and an area of subsidence suggest that the underground fire in the northeast area may be spreading westward. This could lead to problems with regard to the stockpiling of refuse removed from the center low area.

Approximately 5 cubic yards of refuse have been removed from the center low area. In other words, nothing of substance has been done at this point, with regard to his agreed plan. It appears that Janson has placed more material on the berm, in numerous areas, and on the northeast problem area. He appears to have done some work ~~X~~ but not towards following his plan.

The 977 crawler-end loader has been moved to the gate at the entrance to the site. A motor had been installed in tractor but as of 3:45 P.M. they had not been able to get it to run. Janson claims to have spent \$6,000 on it. From the looks of the machine, they apparently did their own work.

Janson stated that once they got the machine running they would work from "daylight to dark" on clearing out the low center area. He also said he wouldn't begin cutting into the berm until I was there. He made no mention of other equipment. Apparently he intends to go forward without any outside help. In any event, at his current rate of progress, it could be months before he gets the center area cleared out, if in fact that is what he intends to do. All of his efforts so far have been towards applying additional cover to the smoke vents. Maybe he hopes the problem will "blow over".

JT/cp

Attachment

cc: Land FOS Manager
Central Region
Ann Carr, A.A.G.
Enforcement Programs

Peoria County

LPC 14380801

DATE: October 4, 1979

Peoria

Janson

TIME: 11:10 - 11:53 A

C. & N.W. R.R.

"Cut" in berm

Smoke venting observed

Randomly dumped refuse?

Center Low Area

Smoke venting observed

Smoke venting observed

Randomly dumped refuse?

Additional material excavated from bluff

subsidence area (warm to the touch)

Refuse excavated from low area? ± 5 yd³

Smoke venting observed

Smoke Venting Observed

Partially burned newspapers July 12, 13 & 14, 1979 in this area

Some excavation of refuse (± 8 bucket loads)

Kickapoo Creek

Scale 1" = 100'